

# IsatPhone 2 (Model 2.1) Firmware 01.00.05

Briefing note  
20.8.2018

IsatPhone 2 (Model 2.1) firmware version 01.00.05 has now been released and is available for download. Please follow the link below:  
<http://www.inmarsat.com/support/isatphone-2-support/>

Firmware version 01.00.05 supersedes the firmware version 01.00.03 that was release in June 2018.

## Recommendations for installation

This is a **recommended** firmware upgrade, meaning that the features introduced by the firmware are important but not critical for the GSPS service including the network and the IsatPhone 2 (Model 2.1) handset.

## Pre-requisites for installation and advice after installation

In order to upgrade the handset's firmware you must have a PC running Windows 10, Windows 8, Windows 7 or Windows XP. The **USB drivers** and **IsatPhone 2 firmware upgrade tool** for IsatPhone 2 (Model 2.1) must be installed.

These can be found on the Inmarsat support website by visiting  
<http://www.inmarsat.com/support/isatphone-2-support/>

## Inmarsat.com

While the information in this document has been prepared in good faith, no representation, warranty, assurance or undertaking (express or implied) is or will be made, nor will responsibility or liability (howsoever arising) be accepted by the Inmarsat group or any of its officers, employees or agents in relation to the adequacy, accuracy, completeness, reasonableness or fitness for purpose of the information in this document. All and any such responsibility and liability is expressly disclaimed and excluded to the maximum extent permitted by applicable law. INMARSAT is a trademark owned by the International Mobile Satellite Organisation licensed to Inmarsat Global Limited. All other Inmarsat trademarks in this document, including the Inmarsat LOGO, are owned by Inmarsat Global Limited. In the event of any conflict between the words of the disclaimer and the English version from which it is translated, the English version shall prevail. © Inmarsat Global Limited 2018. All rights reserved.

Please read the installation guides for the firmware upgrade tool and USB drivers which are also downloadable from the website.

## Installing IsatPhone 2 (Model 2.1) firmware 01.00.05

To install IsatPhone 2 (Model 2.1) firmware 01.00.05:

- a. Ensure that USB drivers and the firmware upgrade tool are installed on your PC
- b. Double click on Inmarsat's firmware upgrade tool and follow on screen instructions.

The firmware upgrade will take approximately 1 - 2 minutes. After installation, you can check the firmware version by switching on the phone and selecting **Menu > Settings > About > Firmware version**

## Fixes and enhancements in this release

- Removed crash for docking usage
- Corrected charging animation after removing wall charger